

P1151 SUBARU

Rear Oxygen Sensor Heater Circuit High Input

Symptoms

- Engine Light ON (or Service Engine Soon Warning Light)

Possible causes

- Faulty Rear Oxygen Sensor
- Rear Oxygen Sensor harness is open or shorted
- Rear Oxygen Sensor circuit poor electrical connection