

P1202 ISUZU
Injector Circuit Open / Shorted Cylinder #2

Symptoms

- Engine Light ON (or Service Engine Soon Warning Light)

Possible causes

- Faulty Fuel Injector #2
- Fuel Injector #2 harness is open or shorted
- Fuel Injector #2 circuit poor electrical connection